

William H. Fisher

Route 1, Box 417 State Rt. 679  
Fincastle, VA 24090

Remington Repair Service

Remington 700 Heavy Barrel 22:250  
SN - B6432968

This Gun fired when loading, It won't  
stay cocked part of the time. I think  
there is a problem with the trigger  
assy.

There is also a problem with the  
latch where you take the bolt  
out of the gun it don't  
come back down when you put the  
bolt back in the gun.