



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00060021	Description/Serial Number B6767200	Repairman - Bruce Travis Date Received - 2/12/2003
Account # - R-	Model 700 Center Fire Caliber: 223 VAR	Estimate Date - 1/24/2003 Current Date - 2/20/2003
Customer HOWARD FORD 26719 WELLBARN ROAD CLOVIS. CA 93611 US	Return To HOWARD FORD 26719 WELLBARN ROAD CLOVIS. CA 93611 US	
Phone (H) Phone (W)	Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M238	CLEAN & INSPECT		

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
00119	GR-TEST	1	1	0	Y
004	ARMS SERV SHIPPING & HANDLING	0	0	0	N
	GR-LABOR	20	20	0	N
Service Total:		21	21	0	

Condition	REC'D W/ MARRED WOOD.				
ProblemNotes	mfg date 1/86 trigger assm dirty and adjusting screws altered sear spring not of remington manufacture. replace trigger assm for \$20.00				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date