

Remington Arms  
14 Hoesler Ave  
Ilion, NY 13357

Repair Guys,

I have had this 722 Remington since about 1969, recently, while hunting varmits, it fired when I put the safety on. NOT a good thing! Luckily it was pointed where it did no harm, but I unloaded it and, after a thorough cleaning of the trigger mechanism, found it now would not go on safety. I took it to a gunsmith, and he said the sear was worn to the point it needed replacing and advised me the factory was doing this for safety reasons, and the parts were not available to him.

OK, here it is, and again varmit season approaches, I hope to see it soon, I'm planning a gopher safari in MT in late May..

Ron Fortier  
202 N. 98th Ave  
Yakima, WA 98908  
509-965-2055  
randyron@outdrs.net

Bolt lock modification  
program Quote customer \$20.00  
for new TA & clean Action  
FCS 5/2/02

Serial Number:

170177

Model: 722



RE00045931