FRED L. MINKER LINDA J. PHILLIPS OWNERS NIKKI ANTICEVICH, MGR

FRED'S HOBBIES & GUNS

360.683.6812 FAX 360.683.3138 FREDSGUN@OLYPEN.COM

349A W. WASHINGTON ST · SEQUIM, WA 98382-3341

Remington Arms Co Att: Arms Service 14 Hoefler Ave Illion, NY 13357

October 20, 2004

Dear Sir.

Enclosed you will find one model 600 (#17255). This rifle was sent to you in December, 2003 to have the safety modification & 1979 recall taken care of (see attached). It was returned to the owner on December 27, 2003. When he took it out to the range this week for the first time, the rifle fired the round in the chamber when he released the safety! His finger was NOT on the trigger!! Just to be absolutely sure, he went through the same procedure again with the same results. Please correct this problem ASAP. If you have any questions you may contact me at the number listed above. Thank you.

Sincerely

Linda Phillips

connector, trig + trig pin usty + 20 not allowing trig. To return to position Replace TPA, checksown completely at H/c. * & charge 230145

4015/4040

17255
Model: 600
RE00086983