

Could not
duplicate customer
Concern -

Check out repair
as needed at 50%
Normal charges

FLS 7/5/00

6-23-00

FRED FRALICK
2145 LAKESHORE DR
CARSON CITY, NEVADA 89704
Phone 775 849 0113
RIFLE - moog 700 .243win. # 320644

Problem -

RIFLE MAY FIRE SEVERAL SECONDS
AFTER TRIGGER IS SQUEEZED
AND RELEASED - WHEN THIS
HAPPENS RIFLE MAY FIRE AS
BOLT IS BEING CLOSED.
THE DELAYED FIRE DOES NOT
OCCUR ON EVERY SHOT BUT
IS INTERMITTENT.

Serial
Number:

320644

Model: 700



RE00010858