

Number: T6237887

Model: 700



RE00018227

12/1/00

It fired once I pushed the safety off.

Upon receipt we could not duplicate the reported
Concern.

Disassembled the Compact trigger assembly. Wet type
lubrication was dripping from the action & housing.

Replace the compact trigger assembly at no charge.

1007
4015
Date Code OR 7/97

Chgs 230145