



RE00001718

Doyell Fenster 1/6/2000

m/700 270 Cal

Would not fire
Then fired on bolt opening

1020
4015

Upon receipt we noted that the rear safety
cam & trigger are missing shipped from being
covered with a brown sticky substance.

Rifle poorly maintained

#26345

Replace complete trigger assembly at
50% of repair cost go ahead