

IF at all possible please

Do not Remove my scope mount

Also please ship my Rifle Back  
By The Quickest means possible  
I'm shipping it REGISTERED MAIL  
(AT A COST OF \$30) I would of shipped  
NEXT Day AIR UPS BUT I'm a man  
OF VERY MODEST MEANS, PLUS my  
WIFE WOULDVE KILLED ME.

Trig. pull screw adjusted beyond length of return  
spr. not allowing proper return of trig. replace  
complete TPA at H/C under warranty

2.5 II  
11/02

1007  
400p

Serial  
Number:

7775242

Model: 7



RE00087324