

Date: 8/9/2005

By: Fred Supry

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Paul Todd Fryer

R.E. Number: 99632

Reason for inspection: FSR

FIREARM

Manufacturer: Rem Model: 700 308

Serial Number: E627716 Date of Manufacture: 3/2/01

Overall external condition: good

Barrel condition: good

Receiver condition: good

Stock condition: good

Bolt/firing pin condition: good

Trigger assembly condition:

Engagement: ok

Adjustments/alterations: Altered TP

Other: Trigger not returning under sear

Headspace:

Function evaluation:

99632

Feeding: _____

Extraction/ejection: _____

Trigger pull: ¹⁶⁵ 6 _____

Manual safety: OK _____

Test firing results (if applicable): _____

DISPOSITION

New. TA n/c - charge 230145

ADDITIONAL COMMENTS

Visible rust on bolt release and
trigger Pin -