

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATTN: FRED ENHOF

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

11/11/90

11/19/90

KY 5-74

6748703

700 30-06

ADL

R 90-30274

ACCESSORY 075TUBE

FROM:

FOOTHILL'S SHOOT CTR
7860 W. JEWELL AVE.
LAKEWOOD CO 80226

SHIP TO:

FOOTHILL'S SHOOT CTR
7860 W. JEWELL AVE.
LAKEWOOD

CO
80226

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE						TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	--	--	--	--	--	-----	-----------	-----	-------------	-------

GUN CONDITION

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"The customer claims the gun fired by itself"

MAIN FAULT

Cannot duplicate complaint, or make rifle otherwise malfunction.
However, searant has been removed from all adjusting screws, outside
jacking. Lockdown is excessive, trigger pull 3.0

PARTS

Offer to replace trigger assembly at
\$ normal price, suggestion of good-
will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE