

6 1994

To.

Remington Arms Co.

Sept 5, 1994

Dear Sirs;

Since 1975, I have owned a
model 700 Remington bolt action 243.


I am an avid fox and coyote
hunter and have drawn great pleasure
using this rifle.

This past winter however, I
experienced problems with the gun firing
after ejecting a spent shell and putting
a new cartridge in the chamber. When
the bolt is pushed forward to load
the new shell, about 50% of the time
the gun will fire.

I took the gun to a gunsmith, and
he said to write to you about this
problem.

I would appreciate some assistance
from you in this matter.


Sincerely
Joe Freitag



40c Freitag
1836Y

Sumner, Ia
50674

UTICA NY 135



Remington Arms Company Inc
Arms Service Division
Ilion, New York

PRODUCT

SERVICE

13357