


J.J. FINNEGAN
84 SUNSET LA. RD.
WASHINGTON DEPOT, CT. 06794

August 3, 1994
84 Sunset Lane Rd.
Washington Depot, Ct. 06794



Dear Service Manager,

I have a problem with a Remington Rifle 30-06,
Model 700 Serial # 6801213.

The rifle fired accidentally when the safety was
released.

I spoke with my local dealer, he recommended
I contact your office.

I purchased the rifle in approximately 1974.

Is there a fix for this condition?

I appreciate any assistance in resolving
the problem.

Sincerely,
John J. Finnegan

