

Dave Faletti
406 S. 9th
Spirit Lake ID 83869
208 623-3786

To: Arms Service Division
Remington Arms Co
Ilion NY 13357

Remington Arms Co.
Ilion, NY 13357

My 700BDL #B6237651 will not keep
the firing pin in the cocked position.
When I put the safety in the
"Safe" position the rifle discharges.
I never had a malfunction before. I
sprayed a light oil into the trigger
assembly to flush it out but that
didn't make a difference. My manual
does not say to oil the trigger assembly.
It looks as if the parts are
stainless steel so I haven't. The
bolt on my rifle locks when it is
on safe. This is a feature I like
which the newer ones don't have. Please
don't change it.

Dave Faletti