

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00047183 Account # - R-	Description/Serial Number E6717397 Model 700 LEFT HAND Center Fire Caliber: 300 ULTRA MAG BDL	Date Received - 5/23/2002 Estimate Date - Current Date - 6/7/2002
Customer DENNY FLEDDERMAN 293 GEORGE ST SAINT MARYS. PA 15857 US Phone (H) (814)-781-7828 Phone (W)	Return To DENNY FLEDDERMAN 293 GEORGE ST SAINT MARYS. PA 15857 US Fax Email	

Problems			
Reported		Found	
M992	FIRED WHEN SAFE RELEASED	M123	FORWARD TO PRODUCT SERVICE FO

Technician's Comments	
ProblemNotes	Action(BBL Bracket) & Trig Assy components Rusty-Appears Rifle was exposed to excessive moisture & not properly cleaned-Replace Trig Assy & Clean Action at N/C as Gesture of Goodwill-Normally this condition would warrant a Repair Charge per D. Sanita

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F32895	700 TRIG ASSB LH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service	Total:	3	


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 ROEFLER AVE
ILION NY 13357

SHIP

TO:

DENNY FLEDDERMAN
293 GEORGE ST
SAINT MARYS PA 15857-1124




PA 158 9-20



UPS GROUND

TRACKING #: 1Z 114 813 03 1189 2467



BILLING: PREPAID

INV#: RE00047163

ASC 3.70 J69K/J64X 14.0 01/2002