

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 93-10736

W/MAG BOX

INITIAL **JJM** CUSTOMER ORDER NO

DATE RECEIVED **04/26/93** DATE OPENED **04/27/93** DATE CODE SERIAL NUMBER **6242274** NEW SERIAL NUMBER MODEL AND GRADE **700 243**
 ACCESSORIES **L/WOOD, L/FOLLOWER L/MAG SPRING SCOPE BASE** *KS 5-69 2ND TIME I*

FROM: *[Signature]* **GRAY, ERNEST**
 2175 PETERSBURG RD
 BOSTON KY 40107

SHIP TO: **GRAY, ERNEST**
 2175 PETERSBURG RD
 BOSTON KY 40107

CUST NO: 078544 C.D.D.L

ACCOUNT NUMBER ACCOUNT NUMBER N/C **059015** PROM. DATE ESTIMATED **5/1/93** VIA **V3705288**

- NEW
- LIGHTLY WORN
- WORN
- VERY WORN
- UNREPAIRABLE
- MARRED

WRITE

REPAIR CHARGE
 EXCISE
 TAX
 INSURANCE
 UPS
 PARCEL POST
 TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Gun fired under safety cover later off

MAIN FAULT *SEND TO R. POTTER*

Unable to duplicate customer concern. However, inspection revealed that more than normal free play was required to move safety. Heavy amount of dry lubrication on trigger assembly, and bolt stop when

ARTS *Trigger movement on bolt stop
 input #1 - 5th
 #2 - 5th*

COMMENTS *Replace trigger assembly completely & check when in position of good*

REPAIRMAN	PROOF	CLEAN <input checked="" type="checkbox"/>	TEST <input checked="" type="checkbox"/>	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/92