

RECEIVING AND ESTIMATING REPORT

COMMENTS

R 93-24482

IAL CUSTOMER ORDER NO.

ATTN: KEVIN CORNELL

TE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

/08/93

11/12/93

EM 10-92

C6750025

700

7MM MAG

BDL

CESSORIES

W/STOPS

DM:

GILLEN, HOWARD
2708 LINCOLN AVE
LA CROSSE

WI 54601

SHIP TO:

GILLEN, HOWARD
2708 LINCOLN AVE
LA CROSSE

WI

54601

CUST NO: 087217 C.O.D. L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059001

WRITE

☐

PROM. DATE

ESTIMATED

VIA

UPS

IN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

"(bolt closes hard)", "automatically fired"

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

YCLE

A1

B1

RIGGER GROUP

B2

E1

F1

OLT ASSY.

B3

E2

F2

ARREL ASSY.

B4

D1

E3

F3

EC. ASSY.

B5

D2

E4

F4

OOD

C1

D3

E5

F5

ETAL

C2

AIN FAULT

Unable to duplicate customer concern of automatically firing. Examination revealed excessive amount of brass in bolt face - upper extractor is upset.

ARTS

COMMENTS

Check out hard closing, replace complete trigger assembly as a gesture of goodwill.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD8925 REV 1/92

PS02699