

Donald F. Garrison
600 West Div. St. 79735 8-3-19-93
Fort Stockton Texas

[Remington Model 700 Cal. 30-06
BDL SPRG.
Serial # 6421105

This Rifle has a Problem With
the Trigger & safety; Especially

after it sits up for a while,
When you work the Bolt you
can't work the safety, and
some times it will fire.

The Trigger is real hard.

I would appreciate it if you could
Have This Rifle Back to me BY or
Before the 25th of Sept. Because I have
a Handicapped ~~Elk~~ Elk Permit to

Hunt. Sept. 29 through Oct. 3.

Thanks Donald F. Garrison
600 W. Div.
Fort Stockton Tex.

Shipped Everything Except 79735
the Stock.