

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 01/08/96  
ENTER REPAIR NUMBER -----> 9529675 MAP=RPMA10 13 47 57  
SERIAL NO: A6927453 NEW SERIAL NO: MODEL: 760  
FROM: (CUST NUM: 131809 ) GEIBEL GA/CAL: 270  
GEIBEL, RALPH TYPE: ADL  
208 NORTH DR ACCESSORIES:

BUTLER  
SHIPPED TO:

PA 16001

DATE CODES: DX 9-73

OTHER ACCESSORIES:

COMMENTS: ATTN JACK KAST

*Check file  
ammo in cab #2*

DATES: TO FROM ASSEMBLER CODE: 1  
RECEIVED 11 20 95 GALLERY 00 00 00 00 00 00 ENTERED BY: JM  
OPENED 11 22 95 PROD SERV 00 00 00 11 27 95 REPAIRMAN: JK-DD  
ESTIMATED 12 04 95 TAG GUNS 00 00 TYPIST:  
PROMISED 00 00 00 REJECTED 00 00 CORRESPONDENT:  
GO AHEAD 00 00 00 CASH RECEIVED: \$ 0.00 BILL TYPE: D IN NO:  
SHIPPED 00 00 00 CLOSED: 00 00 00 CREDIT MEMO:  
BILL TYPE PF1=VIEW DET PF2=REPRINT SEE PF3=PRINT SEE PF5=CUST INT PF9=SHIP

*Not all from the group  
will not be a lot of difference  
same as the ones  
some are segmented  
and others are  
unintegrated  
(14)  
11/11/96*

REPAIR NUMBER: 9529675 NO DATA ENTERED EST LETTER LST 01/08/96  
CUSTOMER NAME: GEIBEL, RALPH 13 48 00

REQUEST: GUN EXPLODED WHEN SIGHTING IN USING NEW AMMO -  
MAIN FAULT: DAMAGE TO GUN RESULTED FROM FIRING A SHELL THAT DEVELOPED  
EXTREME HI-PRESSURE. THE LOCKING LUGS IN THE BBL. EXTENSION  
ARE COMPLETELY SHEARED OFF INDICATING GUN WAS LOCKED UP &  
OPERATING PROPERLY AT THE TIME OF THE INCIDENT.

DATE OF MFG: 09-73 - CONT'D BELOW ----

LABOR: \$ 0.00 REMINGTON ARMS CO. CANNOT BE RESPONSIBLE FOR A CONDITIO  
\$ 0.00 BEYOND OUR CONTROL. EXCHANGE GUN AT A SPECIAL PRICE  
\$ 0.00 STRICTLY AS A GESTURE OF GOODWILL.  
\$ 0.00 REPLACEMENT OFFER - A NEW M/7600 270 IN EXCHANGE  
\$ 207.97 FOR YOUR M/760 AND SUBJECT TO A SPECIAL PRICE -  
\$ 0.00 92-4667  
\$ 0.00 THIS ARM WILL BEAR A SERIAL # \_\_\_\_\_  
\$ 0.00 DD/HAR

REPAIRMAN'S INITS: JK-DD NUM OF WKS: 04 CORRESPONDENT'S INITS:  
TOTAL VALUE: \$ 250.00 PF1 = INQ PF2 = ESTIMATE  
NO MORE DATA AVAILABLE FOR THIS REPAIR