

DEAR: REMINGTON ARMS CORP.

ON NOV. 12, 1995 I WENT TO
A RIFLE RANGE TO SIGHT IN MY
REMINGTON 760 (.270) IN. I SHOT 1
ROUND @ 25 YDS, EVERYTHING WAS FINE.
THE RIFLE WAS OFF A LITTLE.

AFTER FIRING 3 ROUNDS @ 100 YD
I MADE ADJUSTMENT TO MY SCOPE, FIRED
3-MORE ROUNDS FROM A NEW BOX OF
SHELLS. EVERYTHING WAS STILL WORKING
FINE. CHECKED TARGET, GOOD PATTERN BUT
WAS 1 1/2" TO 2" TO LEFT. MADE ADJUSTMENT
TO SCOPE.

SHOT LAST ROUND, ~~THE~~ RIFLE JUMPE
OFF SAND BAGS. AFTER A FEW SECONDS
I LOOKED AT THE RIFLE AND SEEN THAT
THE CLIP + TRIGGER ASSEMBLY BLEW OUT
OF THE RIFLE.

I PUT THE RIFLE BACK IN THE CASE
PICKED UP THE CLIP, TRIGGER ASSEMBLY, AND
ALL THE OTHER PARTS THAT I COULD FIND.

AFTER RETURNING HOME, I TALKED
TO A COUPLE OF PEOPLE ABOUT WHAT COULD
OF HAPPENED OR WHAT COULD OF CAUSE
THE RIFLE TO EXPLODE. BOTH SUGGESTED
TO SEND IT BACK TO THE FACTORY.

SINCERELY,

P.S. PLEASE NOTIFY ME IN REGARDS RALPH GEIBEL