



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00063652	Description/Serial Number A6418999	Repairman - Bruce Travis
Account # - R-	Model 700 Center Fire Caliber: 30 06	Date Received - 4/1/2003
	ADL	Estimate Date -
		Current Date - 4/3/2003
Customer GUNWORKS OF COLORADO 3355 SOUTH YARROW ST E 113 LAKEWOOD. CO 80227 US		Return To GUNWORKS OF COLORADO 3355 SOUTH YARROW ST E 113 LAKEWOOD. CO 80227 US
Phone (H) (303)-986-9412		Fax (419)-818-2730
Phone (W)		Email gunworksco@aol.com

Problems			
Reported		Found	
M238	CLEAN & INSPECT	M123	FORWARD TO PRODUCT SERVICE F

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		1	1	0	

ProblemNotes	mfg date 3/77 small metal machining chip found inside trigger pin hole, replace trigger assm at no charge				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date