

Remington

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00064271	Description/Serial Number A6238099	Repairman - Robert Frink Date Received - 4/15/2003
Account # - R-	Model 700 Center Fire Caliber: 6 MM REM	Estimate Date - 4/11/2003 Current Date - 4/22/2003
Customer BITTERROOT TRADING CO 408 E GLENDALE DILLON, MT 59725 US		Return To BITTERROOT TRADING CO 408 E GLENDALE DILLON, MT 59725 US
Phone (H) (406)-683-2329 X*** Phone (W)		Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	SAFETY MUST BE OFF TO UNLOAD	M238	CLEAN & INSPECT
M994	ACCIDENTAL DISCHARGE	M239	REPLACE TRIGGER ASSEMBLY

Material #		MaterialDesc		Repair			Warranty
				Quantity Needed	Quantity From Inv	Quantity From Kit	(Y/N)
Part							
F26345		700 TRIG ASSB RH		1	1	0	Y
Part Total:				1	1	0	
Service							
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000116		GR-LABOR		20	20	0	N
4000118		GR-CLEAN		1	1	0	Y
4000119		GR-TEST		1	1	0	Y
Service Total:				22	22	0	

ProblemNotes Replace trigger assembly \$20.00. D.S.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date