

Repair Order Number



Repair Order Number RE00061206	Description/Serial Number A6294674	Repairman - Robert Frink Date Received - 2/25/2003
Account # - R-	Model 700 Center Fire Caliber: 270 ADL	Estimate Date - 2/12/2003 Current Date - 3/6/2003
Customer ETHERIDGE GRUBBS 446 HORSE COVE ROAD GILBERT. SC 29054 US		Return To ETHERIDGE GRUBBS 446 HORSE COVE ROAD GILBERT. SC 29054 US
Phone (H) (803)-217-8203 Phone (W)		Fax (803)-252-7454 Email jgrubbs@scana.com

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

ProblemNotes	Trigger assembly poorly maintained. Adjustment and stop screws altered. Replace trigger assembly \$20.00. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date