



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00060807	Description/Serial Number A6469746	Repairman - Robert Frink Date Received - 2/27/2003
Account # - R-	Model 700 Center Fire Caliber: 308 BDL	Estimate Date - 1/31/2003 Current Date - 3/7/2003
Customer DON GRAHAM 1226 GOLDEN HARVEST DR SAINT PETERS. MO 63376 US	Return To DON GRAHAM 1226 GOLDEN HARVEST DR SAINT PETERS. MO 63376 US	
Phone (H) (636)-970-2364 Phone (W)	Fax Email GNG80@MSN.COM	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M238	CLEAN & INSPECT	M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

Condition	REC'D W/ WOOD MARS & W/ WOOD DING @ LEFT F-END.				
ProblemNotes	Quote cleaning action and installing a new trigger assembly under Bolt Lock Modification Program - as received sear would stick down. FLS				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date