

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number
RE00060193

Description/Serial Number
S6338626

Repairman - Robert Frink
Date Received - 1/22/2003

Account # - R-

Model 700 Center Fire Caliber: 270 BDL
SS

Estimate Date -

Current Date - 1/31/2003

Customer
GUNS UNLIMITED INC
4325 SOUTH 120TH ST

Return To
GUNS UNLIMITED INC
4325 SOUTH 120TH ST

OMAHA, NE 68137 US

OMAHA, NE 68137 US

Phone (H) (402)-339-0771
Phone (W)

Fax
Email

Reported		Problems Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F

Material #		MaterialDesc		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F97490		700 SS TRIG ASSB RH		1	1	0	Y
Part Total:				1	1	0	
Service							
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000119		GR-TEST		1	1	0	Y
Service Total:				1	1	0	

Condition	REC'D W/ WATERLIKE MARKS ON STK.				
Problem/Notes	Could not duplicate. Disassembled trigger assembly, found slightly dirty. Replace trigger assembly at no charge. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date