

Serial  
Number:

B6115078

Model: 788



RE00040990

Remington Arms Company, Inc.  
Attn: Arms Service Division/Repairs  
14 Hoefler Avenue  
Ilion, NY 13357

RE: Repair of Rifle

I'm sending a Model 778, Caliber 7-08, Serial number B6115078 for repairs. The nature of the problem is that it has discharged twice on bolt closure.

I can be contacted at the following:

Max W. Gilmore  
1858 N. Farm Road 97  
Springfield, MO 65802

(417) 865-7046  
email: [darrendriskell@email.msn.com](mailto:darrendriskell@email.msn.com)

The best time to reach me by phone is between the hours of 11:00 a.m. and 1:00 p.m. Central Time.

Sincerely,

*Max W. Gilmore*

Max W. Gilmore

40990

2/13/02 Upon receipt we could not duplicate the  
reported concern  
Action & trigger assembly very dirty  
Clean at 1/2 MSP + Test