

Remington.

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 600	Serial Number: 74904
Name: Byron Gilderdale	Date of Purchase:
Address (no PO Boxes): 315 Norfolk Rd	
City: East Canaan	State: CT Zip: 06024
Phone (Daytime): 860 824-9962	Fax: 860 824-0050
E-mail Address: bmgilderdale@SBC.NET	
Please describe your problem:	
Gun fires when safety is Released.	
1979 Recall Never Performed	
Trigger guard bottom plate is warped.	
Trig. Assm. is contaminated w/ a partially dried & sticky	
Lubrication residue causing sear cam to stick to side plates	
Additional Information: (Ammo type, brand, handload specifications, etc.)	
6.5 Rem Mag	
Rep has TPA under recall	
AT. H/C	
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.	

⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

Record the serial number of your firearm before sending it.

to prevent further damage in shipping and

boxes may not be returned.)

to prevent loss or damage.

PS or Parcel Post. Remington is not

I may elect to purchase insurance from

form.htm

11/18/04

Serial Number:

74904

Model: 600



RE00088577

1007
4015/4040