

Date: 12/1/04

By: Bruce Travis SR.

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Byron Gilderdale

R.E. Number: 88577

Reason for inspection: FSR

FIREARM

Manufacturer: Rem. Model: 600

Serial Number: 74904 Date of Manufacture: 8/66

Overall external condition: Good

Barrel condition: okay

Receiver condition: okay

Stock condition: okay

Bolt/firing pin condition: okay

Trigger assembly condition: —

Engagement: —

Adjustments/alterations: —

Other: sticky/binding

Headspace: —

Function evaluation: —

Feeding: —

Extraction/ejection: —

Trigger pull: —

Manual safety: okay

Test firing results (if applicable): —

DISPOSITION

Trig. assm. is contaminated w/ a partially dried + sticky
lubrication residue causing sear cam to stick to side plates

ADDITIONAL COMMENTS

Phase TPA under recall AT N/C