



321 Geri Lane  
Richmond, Kentucky 40475  
(606) 623-1225

MAY 3, 2000

TO: REMINGTON ARMS  
14 HOEFLER AVE.  
ILION, NY 13357

RE: REMINGTON, MODEL 700 BDL, 7mm MAG. CALIBER, SERIAL #C6750210

DEAR SIR:

ONE OF MY CUSTOMERS BROUGHT THE ENCLOSED RIFLE IN FOR RETURN TO THE MANUFACTURER. HIS STORY GOES LIKE THIS-- HE WAS HUNTING WITH THIS RIFLE ON NOVEMBER 18, 1999 WITH REMINGTON FACTORY 7mm MAG NEW AMMO (ENCLOSED). AS HE WAS CHAMBERING A ROUND IT WENT OFF AND HE DESCRIBES WHAT WE CALL FIRING OUT OF BATTERY. THE ROUND EXPLODED BEFORE THE BOLT CLOSED COMPLETELY. HE WAS SERIOUSLY INJURED WITH MULTIPLE METAL FRAGMENTS IN HIS EYES. HE HAS UNDERGONE 4 SURGERIES TO THIS POINT TO REMOVE FRAGMENTS FROM THE BLAST.

HE WANTS THE GUN CHECKED OUT AND REPAIRED IF POSSIBLE. THE EXTRACTOR IS BADLY DEFORMED. IT WOULD BE GOOD IF YOU COULD DETERMINE EXACTLY WHAT CAUSED THE PROBLEM TO BEGIN WITH, WHETHER IT WAS THE AMMO OR GUN RELATED. THE CUSTOMERS NAME AND ADDRESS ARE AS BELOW:

JOHN MOORE  
1716 DRY BRNACH RD.  
IRVINE, KY 40336  
(606) 723-3849

IF THERE ARE ANY PROBLEMS OR QUESTIONS, PLEASE GIVE ME A CALL AND THANK YOU FOR YOUR ATTENTION TO THIS SMALL MATTER.

*M. Latham*  
M. LATHAM,  
OWNER

**8981**

R.S. Ammo is below styrofoam