

Repair Order Number



Repair Order Number RE00078433	Description/Serial Number 7762985	Repairman - Bruce Travis Date Received - 3/9/2004
Account # - R-	Model 7 Center Fire Caliber: 7 MM 08 LAM	Estimate Date - Current Date - 3/13/2004
Customer HENRY GREER 306 SMITH HOLLOW RD BLAINE. TN 37709 US		Return To HENRY GREER 306 SMITH HOLLOW RD BLAINE. TN 37709 US
Phone (H) (865)-573-4501 Phone (W)		Fax (865)-933-0777 Email

Problems			
Reported		Found	
M992	UNINTENTIONAL FIRINGS	M123	FORWARD TO PRODUCT SERVICE F

		Repair			
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F92458	7 TRIGGER ASSB	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		1	1	0	

ProblemNotes	upon receipt we found the trigger seized up in the rearward position from rust between the inside side of the housing and trigger.safety detent spring also found rusty. replace complete trigger assm at no charge good-will gesture.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date