

# AUDUBON FORD



TO WHOM IT MAY CONCERN,

MY CONCERN IS THAT 3 TIMES THIS RIFLE HAS FIRED WHEN LOADING A BULLET IN THE CHAMBER WHEN CLOSING THE BOLT. THIS DOES NOT HAPPEN ALL THE TIME AND I HAVE TAKEN TO A GUNSMITH WHO TRIED TO FIX IT BUT IT DID IT AGAIN AFTER HE HAD WORKED ON IT. THE SAFETY CONCERNS HAVE ME EXTREMELY WORRIED. IF YOU WOULD PLEASE LOOK INTO THIS MATTER I WOULD GREATLY APPRECIATE IT.

THANKS,  
DAVID GAFFNEY  
5847 LAKE SHADOW  
BATON ROUTE, LA. 7081  
(H)(225) 753-7967  
(W)(225) 293-8900