

9/96

DIR

Remington Arms Co. Inc.
Arms Service Division
14 Hoefler Avenue
Ilion, NY. 13357

To Whom It May Concern:

Please repair or replace the Remington model 700 muzzleloader. (Serial # ML028219)

Problem:

- 1.) It won't always cock when the bolt is closed.
- 2.) It discharges without pulling the trigger / after the safety is off.

Thank you for your attention to this matter.

James E. Gatton

James E. Gatton
1607 180th St.
LuVerne, Iowa 50560
515-295-3921

*Seamcam damaged.
Also TPA & trigger
completely broken
* #230145*

ML028219

Model: **700ML**



RE00091894