

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
Service
XCF.S.R ORDER
94-13506INITIAL
F.P.S.

CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ACCESSORIES

W/STUDS

L/SIGHTS

700 7MM MAG ADL

FROM:

SHIP TO:

GUNWORKS, THE
162 E. YOSEMITE AVE
MANTECA

CA 95336

GUNWORKS, THE
162 E. YOSEMITE AVE
MANTECACA
95336

CUST NO: 096190 CLO.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

5-23-94

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

20.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Left Mfg Pk2 could not duplicate the reported problem. Removal
of the trigger assembly revealed that the 3 trigger adjustment screws have had the
screws removed and they have been re-set. The trigger pull measured 2.0

PARTS

COMMENTS

#263-5 Trigger Assembly

Replaced complete trigger assembly and
cleaned action at 1/2 round replacement
cost, as quoted at 1/2 round

GO ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

BD6925 REV. 1/94

to R/S 5/24/94