

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-13872

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/21/94

04/22/94

PQ 6-78

A6619537

700 30-06

BDL

ACCESSORIES

W/STUDS

W/SWIVELS

SCOPE BASE

FROM:

SHIP TO:

GUN EXCHANGE INC
5317 W 65TH ST
LITTLE ROCK

AR 72209

GUN EXCHANGE INC
5317 W 65TH ST
LITTLE ROCKAR
72209

CUST NO: 000191 ILION

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Unable to duplicate upon receipt. Examination reveals no fault in barrel, trigger, and trigger assembly. Removal of scope safety beam, a gunning substitution was found built upon back side. Left side a good cleaning.

PARTS

COMMENTS

Trigger Pin #1/2 in
 Gun left .008
 #26345 Trigger Assembly

Replaced complete trigger assembly and then action at 1/2 normal replacement cost, in question of good will.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
TAL		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

to A/S 5/19/94