

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
ServiceR ORDER
94-12608

INITIAL FPS	CUSTOMER ORDER NO.					
DATE RECEIVED 04/11/94	DATE OPENED 04/11/94	DATE CODE EP 10-67	SERIAL NUMBER 311272	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	RDL
ACCESSORIES W/STUDS						

FROM:

GREENWAY, LARUE
RR 1
BOX 214
MONTOURSVILLE

PA 17754

SHIP TO:

GREENWAY, LARUE
RR 1
BOX 214
MONTOURSVILLE

PA 17754

CUST NO: 095682 C.O.D.

ACCOUNT NUMBER 063103	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED 5-19-94	VIA V5103951
GUN CONDITION		REPAIR CHARGE 20		
☐ NEW		EXCISE		
☐ LIGHTLY WORN		TAX		
☒ WORN		INSURANCE		
☐ VERY WORN		UPS 8		
☐ UNREPAIRABLE		PARCEL POST		
☒ MARRED		TOTAL 28.00		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP					E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Mfg. 10-67 Gun did not malfunction by slamming bolt & retaining safety as desired. After trigger adjustment, seems there have been a field adjustment of the factory. We do not recommend that the trigger be adjusted outside of the factory. Exchange trigger assy. at special price strictly as a gesture of good will.

PARTS	COMMENTS	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	Trigger pull measured 2 to 2 3/4 LBS as desired. new lift was .0095	R.B.S.					
		GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS02939