



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00088734	Description/Serial Number B6437222	Repairman - Richard Hilts Date Received - 12/6/2004
Account # - R-	Model 700 Center Fire Caliber: 243 ADL	Estimate Date - Current Date - 12/10/2004
Customer JAMES GUM 159 HARRISON DRIVE WESTON, WV 26452 US		Return To JAMES GUM 159 HARRISON DRIVE WESTON, WV 26452 US
Phone (H) (304)-269-2271 Phone (W)		Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M994	DISCHARGED WHEN LATCH PUSHED	M994	DISCHARGED WHEN LATCH PUSHE

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	N
Part Total:		1	1	0	
Service					
4000119	GR-TEST	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000118	GR-CLEAN	1	1	0	Y
Service Total:		2	2	0	

Condition	STOCK IS MARRED				
Problem/Notes	trigger assembly is contaminated with sticky lubrication residue causing sear to stick to side plate replace trigger at 1/2 msp				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date