

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-25964

INITIAL

CUSTOMER ORDER NO.

LCS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/10/91

12/12/91

6265287

700 7MM MAG

BDL

ACCESSORIES

W/STUDS

WS B-692ND TIME

FROM:

SHIP TO:

HANCZARKY, PETER
47A SKYLINE DR
RD 1
MELROSE
USA

NY 12121

HANCZARKY, PETER
47A SKYLINE DR
RD 1
MELROSE
USANY
12121

CUST NO: 054688 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER NYC

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	<i>"The problem with the gun is as follows: When you load it and close the bolt, the shell automatically goes off."</i>					
BOLT ASSY.						
BARREL ASSY.						
REC. ASSY.						
WOOD		B5	C1	D2	E4	F4
METAL			C2	D3	E5	F5

MAIN FAULT

As noted, the trigger assembly was inoperable. Upon closing the bolt, the firing pin simply fell back down on the cocking cam. Inspection of the trigger assembly revealed it was contaminated with a sticky substance, to the point that the rear safety cam was stuck to the side plate of the trigger assembly. This rifle has not been properly maintained.

PARTS

COMMENTS

Clean paint trigger assembly, if possible. If not, offer replacement assembly at a prorated cost, as a gesture of good-will.

**Note - This rifle is 22 years old.*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE