

COMMENTS

1 HEDGPETH, BILLY JOE ROUTE 2 BOX 45 DEKALB MS 39328	1 SHIP TO: HEDGPETH, BILLY JOE ROUTE 2 BOX 45 DEKALB MS 39328
---	--

Quote

USA 4271-3826-2023-0264
Ph 601-743-8443 Exp 12/91

☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED

Gcm fits without Touching Trigger

Triggen assembly is contaminated with sticky, gummy residue - internal triggen parts are not moving freely. Res. safety chain is sticky on triggen assembly side plates. Sticky residue on bottom of receiver also. Res. left too long & not been properly maintained. Triggen pull $4\frac{3}{4}$ pounds.

06345	Tugger	AS 0007	offer to clean present tugger, or possibly (if possible) (M) we can install a new tugger currently at ± normal cost, as a gesture of good-will, if this will little restore confidence in the corp.
00982	1100 Follow-up		
00980	1100 RB	SS 22/83	

3711 - a 700 Watt Assn
to Customer 2/11/91 Ed
also Local Assn in 20/250

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

Prove 2/11/91 OFFICE COPY 14021 REV 7/90

OFFICE COPY

4023 064 3,00