

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-10227

INITIAL CUSTOMER ORDER NO.

W/ SOFT CASE

FJB

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

03/18/94

03/21/94

PZ 6-75

6881186

700 243

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

HIGHSMITH GUNS
3968 WEST 300 SOUTH
NEW PALESTINE

IN 46163

HIGHSMITH GUNS
3968 WEST 300 SOUTH
NEW PALESTINE

IN 46163

CUST NO: 014391 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

5-6

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	B1	B1				
TRIGGER GROUP	B2	B2			E1	F1
BOLT ASSY.	B3	B3				
BARREL ASSY.	B4	B4		D1	E3	F3
REC. ASSY.	B5	B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Upon receipt we could not install bolt assembly. The bolt was
where was covered with a heavy, thick, and gummy substance. The receiver
would not function as designed. We could not determine the unintentional
drinking reason. They said, measured 4 1/2 in. 5 in. 6 in. 7 in.

PARTS: The action is also covered with the gummy substance. Rifle needs a good
cleaning. More than normal sprayer required at time to remove safety.

COMMENTS: Replace receiver trigger assembly
& clean action at 1/2 normal
replacement that as gather 4 good ones

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
BWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1