

REPAIR GUN UPDATE FUNCTION: N (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 10/06/92
ENTER REPAIR NUMBER -----> 9216123 14 19 05

C6504792
FROM: (CUST NUM: 007822) SPORTSMAN
SPORTSMAN INC, THE
C/O NBS
1511 HWY 1 S
GREENVILLE
SHIPPED TO:

MODEL: 700
GA/CAL: 270
TYPE:
ACCESSORIES: L/WOOD
L/SIGHTS

MS 38701

DATE CODES: LK 2-90
OTHER ACCESSORIES:

COMMENTS: W/FLOOR PLATE, MAG BOX, MAG SPG, FOLLOWER, SCREWS

DATES:		TO	FROM	
RECEIVED	07 31 92	GALLERY	09 29 92	10 05 92
OPENED	08 11 92	PROD SERV	08 14 92	08 19 92
ESTIMATED	08 21 92	TAG GUNS	00 00	
PROMISED	00 00 00	REJECTED	00 00	
REPAIRED	00 00 00	CASH RECEIVED:	\$ 0.00	BILL TYPE: W
SHIPPED	00 00 00			

BILL TYPE PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9216123 CHARGE (AWAIT RESP) EST/LETTER LSTD 10/06/92
CUSTOMER NAME: SPORTSMAN INC, THE 14 19 15

REQUEST: "...RIFLE FIRED WHEN SAFETY WAS SWITCHED FROM "SAFE" TO
"FIRE" "

MAIN FAULT: CAN NOT DUPLICATE COMPLAINT - RIFLE TRIGGER ASSEMBLY AND
SAFETY OPERATES PROPERLY IN EVERY ASPECT, RIFLE CAN NOT
BE MADE TO MALFUNCTION IN ANY WAY
TRIGGER PULL 5 1/2 LBS., SEAR LIFT .011"
DATE OF MFG: 2/90

LABOR: \$ 0.00 OFFER TO RETURN RIFLE AS IS OR TO REPLACE TRIGGER
\$ 0.00 ASSEMBLY AT 1/2 PRICE AS GESTURE OF GOOD WILL TO
\$ 25.00 BETTER RESTORE CONFIDENCE IN THE RIFLE
\$ 0.00 CLEAN, TEST
\$ 0.00 25 D/A 8445963
\$ 0.00 RF:CMS

REPAIRMAN'S INITS: RF NUM OF WKS: 03 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 30.00 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR