

REMINGTON ARMS COMPANY, INC.
ARMS SERVICE DIV.
LLION, N.Y. 13357

JAN. 14, 1992

BILL HAYNES
2804 PINEY PLAINS RD.
CARY, N.C. 27511

MODEL 700
SERIAL NUMBER B6284415
BOLT SERIAL NUMBER 4415

MY 700 AFTER LOADING OCCASIONALLY WILL NOT COCK AND MUST
BE RE-COCKED AGAIN BEFORE FIRING. ALSO OCCASIONALLY AFTER
LOADING WHEN THE SAFETY SWITCH IS PUSHED TO THE "F" POSITION
THE RIFLE HAS FIRED WITHOUT PULLING THE TRIGGER.

THIS IS THE BEST RIFLE I HAVE EVER OWNED AND I HAVE BAGGED MY
LIMIT OF DEER EVER YEAR SINCE I BOUGHT IT.
IF YOU HAVE ANY QUESTIONS ON THIS PLEASE CALL ME AT 919-248-4115
(DAY TIME) AFTER 4:00 P.M. 919-851-1155.

SINCERELY,

Bill

BILL HAYNES