

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-24362

INITIAL CUSTOMER ORDER NO.

LCS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/22/91

11/26/91

KI 5-88

C6251170

700 30-06

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

SHIP TO:

HILLS INC
1720 CAPITAL BLVD
RALEIGH
USA

NC 27604

HILLS INC
1720 CAPITAL BLVD
RALEIGH
USANC
27604

CUST NO: 004393 ILION L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

12-9

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Handwritten: fired 3 times when safety is put in fire position, without pulling trigger

Handwritten: Trigger assembly rusted from unknown source - internal parts not moving freely nor properly - trigger activation not consistent nor positive. Problem could not be duplicated, but with cone of trigger assembly, malfunction could occur.

PARTS

COMMENTS

Handwritten: Replace trigger assembly at no charge, as gesture of good-will

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

BWT

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8

PS03100