

Repair Order Number



| | | |
|--|---|--|
| Repair Order Number RE00064095 | Description/Serial Number E6795012 | Repairman - Dale Lewis Date Received - 4/9/2003 |
| Account # - R- | Model 700 Center Fire Caliber: 308 ADL SYNTHETIC | Estimate Date - Current Date - 4/16/2003 |
| Customer JOHN HAYES RR1 BOX 548 C WARREN CENTER. PA 18851 US | Return To JOHN HAYES RR1 BOX 548 C WARREN CENTER. PA 18851 US | |
| Phone (H) (570)-395-0169 Phone (W) | Fax Email | |

| Reported | | Problems | | Found | |
|----------|---|----------|------------------------------|-------|--|
| M123 | FORWARD TO PRODUCT SERVICE FOR INSPECTION | M123 | FORWARD TO PRODUCT SERVICE F | | |
| M990 | SAFETY IS STIFF | | | | |
| M992 | WILL SOMETIMES FIRE ON SAFE | | | | |

| | | Repair | | | |
|-------------------|-------------------------------|----------------------------|------------------------------|------------------------------|---------------------------|
| <u>Material #</u> | <u>MaterialDesc</u> | <u>Quantity Needed</u> | <u>Quantity From Inv</u> | <u>Quantity From Kit</u> | <u>Warranty (Y/N)</u> |
| Part | | | | | |
| F26345 | 700 TRIG ASSB RH | 1 | 1 | 0 | Y |
| Part Total: | | 1 | 1 | 0 | |
| Service | | | | | |
| 4000294 | GR-CHECK TPA | 1 | 1 | 0 | Y |
| 4000104 | ARMS SERV SHIPPING & HANDLING | 0 | 0 | 0 | Y |
| 4000119 | GR-TEST | 1 | 1 | 0 | Y |
| Service Total: | | 2 | 2 | 0 | |

| | | | | | |
|-----------------------|---|--------------|-------------|---------------|----------------|
| ProblemNotes | safety arm works hard..small metal chip found inside of housing...action and trig assm slightly dirty...clean action and replace trig assem at n/c per rproduct service | | | | |
| Repairman | Proof | Clean | Test | Target | Pattern |
| Gallery Tester | Date | Date | Date | Date | Date |