

Dear Remington / SAFETY MODIFICATION PROGRAM.

I AM SENDING THIS GUN TO YOU FOR THE REPAIR
OF THE BOLT LOCK - TRIGGER REPAIR RECALL.
I VISITED YOUR WEB-SITE AND REVIEWED THE
INFO. THANKS TO YOUR ~~WEB~~ WEB SITE I HAD
THE HEADS UP AT THE SHOOTING RANGE. THIS
GUN MISTAKES BALLY. I JUST ACQUIRED THIS GUN
AND IT IS VERY ACCURATE AT THE RANGE. BUT IT
IS VERY DANGEROUS. PLEASE HANDLE WITH
CARE, IT IS A BEAUTIFUL GUN, AND I HOPE
IT CAN BE REPAIRED.

Dan Haaser
P/N (260) 668-7005

3495 W. LANDIS RD
ANGOLA IN 46703

Date Code
BY 1/74

dmhaaser@earthlink.net

4/1/03

10440
4015 / 4006
Action & trigger assembly
Coly & stop screws
Replace trigger assembly 20.00
D.H.A.

6704836

Model: 700



RE00063854