



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00058977	Description/Serial Number A6459623	Repairman - Robert Frink Date Received - 1/9/2003
Account # - R-	Model 700 Center Fire Caliber: 243 BDL	Estimate Date - Current Date - 1/20/2003
Customer HUDSON MACHINE & TOOL ATTN WARREN HOWE 1750 RIDGEWAY ST HAMMOND, WI 54015 US	Return To HUDSON MACHINE & TOOL ATTN WARREN HOWE 1750 RIDGEWAY ST HAMMOND, WI 54015 US	
Phone (H) Phone (W)	Fax Email	

Reported		Problems Found	
M992	ACCIDENTAL DISCHARGES	M123 M238 M239	FORWARD TO PRODUCT SERVICE F CLEAN & INSPECT REPLACE TRIGGER ASSEMBLY

Material #		MaterialDesc		Repair		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part		F26345 700 TRIG ASSB RH				1	1	0	Y
Part Total:						1	1	0	
Service		4000104 ARMS SERV SHIPPING & HANDLING				0	0	0	Y
		4000116 GR-LABOR				20	20	0	N
		4000118 GR-CLEAN				1	1	0	Y
		4000119 GR-TEST				1	1	0	Y
Service Total:						22	22	0	

ProblemNotes	Very clean trigger assembly. Safety detent not working. Install a new trigger assembly, clean action \$20.00 under Bolt Lock Modification Program. FLS 1/10/03.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date