

RECEIVING AND ESTIMATING REPORT

INITIAL RLP		CUSTOMER ORDER NO.		COMMENTS <i>File</i>	
DATE RECEIVED 09/12/90	DATE OPENED 09/24/90	DATE CODE AD 3-81	SERIAL NUMBER B6317109	MODEL AND GRADE 700 25-06	ORDER R 90-24559
ACCESSORIES W/STUDS		SCOPE BASE L/ REAR SIGHT			

FROM:

HENRY'S GUNS 'R' US
RT 11 N MAIN ST
RT 1 BOX 442
MT JACKSON VA 22842

SHIP TO:

HENRY'S GUNS 'R' US
RT 11 N MAIN ST
RT 1 BOX 442
MT JACKSON VA 22842

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"The rifle will go off prematurely. It has gone off on 2 occasions with safety on."

MAIN FAULT

Cannot duplicate complaint - it is mechanically impossible for this rifle to fire with the safety on. Trigger assembly has been improperly adjusted outside factory. Trigger pull is below spec at 2 1/4# and over-travel is insufficient. Seem lift measured to be .014"

PARTS

Either (1) re-adjust present trigger assembly to proper specification if possible or (2) send gun back for new trigger assembly at 1/2 normal price, as gesture of good will.

Rifle is 9 years old.

REPAIRMAN <i>RLP</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88

PS03153