

Enclosed is a Rem 700 BDL
in 25-06. cal. The rifle will
go off pre-maturely. It has
gone off on 2 occasions with
Safety on. Please repair.
I need gun back by Nov. 15th

4559

Thank you.

HENRY'S GUNS "R" US
Route 11, N. Main Street
Route 1, Box 442
Mt. Jackson, VA 22842
(703) 477-3447

anxious with safety ^{on} "E".

Cannot duplicate complaint - it is mechanically
possible for this rifle to fire with the safety on.
gun assembly has been improperly adjusted outside factory.
Trigger pull is below spec. at 2 1/4 # and over-travel is insufficient.
in lift measured to be .014"

Either (1) re-adjust present trigger
assembly to proper specification if
possible or (2) send gun to factory for new
trigger assembly at $\pm$ normal price,
as gesture of good-will.

Rifle is 9 years old.

REPAIRMAN

GALLERY TESTER

PROOF

DATE

CLEAN

DATE

TEST

DATE

TARGET

DATE

PATTERN

DATE

OFFICE COPY

RD6925 REV. 6/88

PS03154