

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product **R** SERVICE

ORDER 94-25956

INITIAL
FPS

CUSTOMER ORDER NO.

W/BTM. HALF OF SCOPE MOUNTS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

09/09/94

09/12/94

CE 4-84

B6570401

700 30-06

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

SHIP TO:

HILL, JOHN W.
859 DENTON RD.
CEDARTOWN

GA 30125

HILL, JOHN W.
859 DENTON RD.
CEDARTOWN

GA 30125

CUST NO: 103286 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☒ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Gun fired when closing the bolt with the safety on
Mfg. 4/84 Unable to duplicate customer concern as rec'd. trigger parts were gummed up from solidified gun oil. whole underside of action dirty and sticky. Only a light film of light oil is required to prevent rusting. See owners manual. Exchange trigger Assy. at a special price as a gesture of good will and to restore customers confidence in the rifle.

PARTS

Trigger Assy Complete

COMMENTS

Trigger pull measured 3 1/2 to 3 3/4 lbs as rec'd. rear lift was .013

- Bolt Stop Sticks as rec'd.*
- Sear was sticking in trigger housing*
- Safety off force seems heavy*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS03156