

5-25-1994

I talked to a man, first name Dave, at your booth in Minneapolis, MN at the 1994 NRA annual meeting. He told me to send you this rifle, Remington model 700 Serial No 6719070.

This rifle has fired by itself twice when the safety was taken off. After this happened I took the rifle to a person who does some work on guns - Not A Gunsmith - and he did some adjusting on the trigger pull. I do not feel comfortable using this rifle as it is.

Please let me know in writing what you do to this rifle.

I have two more models 700s if there might be a problem with either of these rifles let me know and I will send them to you.

7mm Remington Mag. Serial B6277560

3006 Springfield Serial B6279084

After this rifle discharged when the safety was taken off I tried it with the chamber empty. When the safety was taken off the firing pin was released (Fired) on approx. $\frac{1}{2}$ the times.

I had no problem with this rifle because of the accidental firing.

Thank You
Gordon L. Herrgard
Gordon L. Herrgard
RR1 Box 22
Deer River, MN 56636

TEST	TARGET	PATTERN
DATE	DATE	DATE

RD8925 REV. 1/84

PS03170