

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-33080

CUSTOMER ORDER NO.

FIS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/16/94

11/17/94

LE 2-84

R6549075

700 300 WIN

MAG/BDL

ACCESSORIES

W/STUDS

FROM

SHIP TO:

HANN, JERRY
41 RAYNHAM AVE
GANDER, NLFD.
CANADA

AOG 1P0

HANN, JERRY
41 RAYNHAM AVE
GANDER, NLFD.
CANADA

AOG 1P0

CUST NO: 108377 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER WC

059015

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

When bought, the trigger, new safety cam, and bolt stop release were working sluggish. Examination revealed that the Compact action and trigger assembly are covered with dirt and a heavy build up of a sticky substance. The 1984 manufacture rifle has been poorly maintained.

PARTS

COMMENTS

When discussing our findings with customer via telephone on 11/30/94, he became very upset and was demanding regarding the condition. Therefore, stating as a gesture of good will agreed to clean action & replace the Compact trigger assembly.

#56345

Replace Compact trigger assembly & clean the action at the

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94