

RECEIVING AND ESTIMATING REPORT

COMMENTS

To Product Service

ORDER
R93-25212

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED 11/16/93	DATE OPENED 11/19/93	DATE CODE DP 9-67	SERIAL NUMBER 96645	NEW SERIAL NUMBER	MODEL AND GRADE 600 243 WIN
---------------------------	-------------------------	----------------------	------------------------	-------------------	--------------------------------

ACCESSORIES W/STUDS W/SWIVELS

FROM: *Staffell*
HITCHIN POST SPORTS
124 N MONTANA
DILLON

MT 59725

SHIP TO:
HITCHIN POST SPORTS
124 N MONTANA
DILLON

MT
59725

CUST NO: 003292 C.O.D L

ACCOUNT NUMBER ACCOUNT NUMBER W/C

WRITE ☐

PROM. DATE ESTIMATED VIA
UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE *20.*
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			F1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *10/19/93, upon receipt, could not duplicate customer concern. Examination of action and trigger assembly revealed that the rifle was poorly maintained. Over cleaned with oil, and heavy build up of lubrication. Safety assembly works better than normal.*

PARTS

COMMENTS

Customer complaint trigger pump and clean action at 1/2 normal cost

Go ahead!

REPAIRMAN <i>MS</i>	PROOF	CLEAN	TEST	TARGET	PATTE
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.

PS03234